A periodic surveillance must be conducted of each school building that contains ACBM or is assumed to contain ACBM at least once every 6 months. Visually inspect all areas that are identified in your AHERA Management Plan to observe current conditions. Note both damage and change in condition by circling the appropriate category below using the comment section for details. Date and sign this surveillance then submit a copy of the record to the Designate Person for inclusion in the AHERA Management Plan.

DO NOT TOUCH ASBESTOS - CONTAINING MATERIAL WITHOUT PROPER TRAINING

Bolton Primary School (BPS)								
Material	Location	Quantity	Damaged	Changed				
Cement Asbestos Board	Chalkboards presumed throughout (none observed during inspection but may be obscured by cork boards or white boards)		Yes (No)	Yes No				
Asbestos Insulated Wiring	Potentially throughout (previously observed in stage area that has since been remodeled)		Yes No	Yes No				
Covebase/Mastic	Throughout		Yes No	Yes No				
Fire Door	Throughout		Yes No	Yes No				
Gypsum Wallboard	Throughout		Yes No	Yes No				
Lay-in Ceiling Tile	Throughout		Yes No	Yes No				
Sheet Floor Covering	Throughout		Yes No	Yes No				
Vinyl Floor Tile	Throughout		Yes No	Yes No				
Window Glazing Compound	Throughout		(es) No	Yes No				
Air Cell/Hard Fittings	Throughout the building in inaccessible areas		Yes No	Yes No				
Asbestos Pipe Insulation	Throughout the building in inaccessible areas		Yes No	Yes No				

Comments	Localized LCT damage in nurses room; water damage to pipe insulation in custodial closet on northeast side school; localized gyp damage in hall near room A14; window glazing cracking and missing in some areas throughout courtyard and southeast side of school.							
By : Tay	lor Cook	Title:	IH Tech	Date of Observation:	10/19/2022			