A periodic surveillance must be conducted of each school building that contains ACBM or is assumed to contain ACBM at least once every 6 months. Visually inspect all areas that are identified in your AHERA Management Plan to observe current conditions. Note both damage and change in condition by circling the appropriate category below using the comment section for details. Date and sign this surveillance then submit a copy of the record to the Designate Person for inclusion in the AHERA Management Plan.

DO NOT TOUCH ASBESTOS - CONTAINING MATERIAL WITHOUT PROPER TRAINING

Material	Location	Quantity	Damaged	Change
Hard Fittings/Fiberglass	Custodial closet, plumbing wall, at hot water tank; presumed in inacccessible walls/ceilings.		Yes No	Yes (No
Fire Door	Throughout		Yes(No)	Yes (No
Gypsum Wallboard	Throughout		Yes (No)	Yes (No
Sheet Floor Covering	Throughout		Yes (No)	Yes (No
Vinyl Floor Tile	Throughout (9"x9" observed in custodial restroom)		Yes No	Yes
Window Glazing Compound	Throughout on exterior windows		Yes (No)	Yes (No
	·			l closets.