Lead in Water Test Results Summary: WLWV District Operations Center

Notes:

• The lead in water Action Level is 15 parts per billion (ppb).

Any fixture testing at or above the action level of 15 ppb is immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up testing.

• A "ND" or "non-detect" test result indicates the sample measured below the minimum detection limit of [1] ppb.

Legend:

• Test results greater than or equal to the Action Level of 15 ppb are highlighted in red and precede an "Action Req." (Action Required) value in the "Initial Level" or "Final Level" column.

• Test results from 12 ppb to 14.99 ppb (near the Action Level) are highlighted in orange and precede a "High" value in the "Initial Level" or "Final Level" column.

• Test results from 5 ppb to 11.99 ppb are highlighted in yellow and precede a "Moderate" value in the "Initial Level" or "Final Level" column.

• Test results less than 5 ppb are not highlighted and precede a "Low" value in the "Initial Level" or "Final Level" column.

		Initial	Initial Test	Initial	Final	Final Test	Final
Fixture Location Description	Fixture ID #	Test Date	Result (ppb)	Level	Retest Date	Result (ppb)	Level
A118- Staff faucet. Repair shop & storage	1922001-001SF	3/4/2025	ND	Non-Detect		ND	Non-Detect
A112- Water bottle filler.	1922001-002WB	3/4/2025	ND	Non-Detect		ND	Non-Detect
A110- Bathroom faucet. Women's . Left	1922001-003BF	3/4/2025	ND	Non-Detect		ND	Non-Detect
A110- Bathroom faucet. Women's . Right	1922001-004BF	3/4/2025	ND	Non-Detect		ND	Non-Detect
A109- Bathroom faucet. Men's Restroom. Right	1922001-006BF	3/4/2025	ND	Non-Detect		ND	Non-Detect
A109- Bathroom faucet. Men's Restroom. Left	1922001-007BF	3/4/2025	ND	Non-Detect		ND	Non-Detect
A108- Kitchen Faucet. Lunch Room	1922001-009KF	3/4/2025	ND	Non-Detect		ND	Non-Detect